


**ART GALLERY**

Art Gallery



Roof Replacement in Progress



Roof Replacement in Progress



Ship's Ladder Installation

**Scope:** Drawings, Details, Specifications and Quality Observations for Roof Replacement and Fall Protection Upgrades

**Services Provided:** Several roof areas were replaced with a new high performance insulated roofing system. Terminators at the natural stone copings were installed without affecting the heritage features of the building. Fall protection guardrails were upgrade along with a new ship's ladder to enable roof access, which originally involved crawling through a window and walking across a skylight frame. Rooftop duct work was also replaced with new.

**Construction Value:** \$250,000.00